ATTENTION ALL PILOTS:
The VOR is operational!
Please ensure that the latest approach plate is used.